

SDMS US EPA REGION V -1

**SOME IMAGES WITHIN THIS
DOCUMENT MAY BE ILLEGIBLE
DUE TO BAD SOURCE
DOCUMENTS.**

158126

St. Clair Co. - S.F.

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. 810609

IL 4/97

ILS-000-001-434

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Republic Steel Corporation

Street P.O. Box 6778

City Cleveland

State Ohio

Zip Code 44101

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Tudor Works

Street 6th Street

City East St. Louis County St. Clair State Ill. Zip Code 62201 ✓

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gubanc, D. M., Solid Waste Mgmt. Engr.

Phone (216) 622-5916

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) Unknown

To (Year) 1913 - sold 1965 (last parcel)

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☒ Unknown
- 11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☒ Other (Specify)

Blast furnace and
coke ovens

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which this site is located.

000595

981

Notification of Hazardous Waste Site

Side Two

Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

Use the "total facility waste amount" space to give the estimated combined quantity (volume) of hazardous wastes at the site in cubic feet or gallons.

Use the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) Unknown

Total Facility Waste Amount

cubic feet

gallons

Total Facility Area

square feet

acres 12.5 13 14

Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, cities or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a sketching map showing the site location.

Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, ponds, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide other information or comments which help describe the site conditions.

Signature and Title:

Signature of person or authorized representative (owner, plant managers, superintendents, or attorneys) of persons required to sign the form and provide a signature (if different than address). For other persons providing information, the signature is optional. Check the boxes which best describe the relationship to the site of the person signing. If you are not required to sign, check "Other".

Name W. L. West, Director
Environmental Control

Street

City

State

Zip Code

Signature

W. L. West

Date 6/8/81

- ☐ Owner, Present
- ☒ Owner, Past
- ☐ Transporter
- ☐ Operator, Present
- ☐ Operator, Past
- ☐ Other

Republic Steel

Republic Steel Corporation
General Offices: Republic Building
Environmental Control
PO Box 6778
Cleveland OH 44101

June 9, 1981

WL West
Director
WB Tucker Jr.
Assistant to the Director
CM Brown
Assistant Director—Air

U.S. EPA Region 5
Sites Notification
Chicago, Illinois 60604

Subject: Superfund Notification Forms (EPA Form 8900-1)

The subject forms for inactive and/or closed sites owned and/or operated by Republic Steel Corporation are attached. Fourteen (14) forms are submitted.

Sincerely,


W. L. West
Senior Environmental Engineer

Director

Assistant Director

W. L. West

JUN 11 1981

8 547- OUT-11 Region